

Silicon enemy number one

by Gary Blevins, N.D. Mech. Eng.

High levels of airborne dust in South Africa increase the risk of oil contamination.

External contamination of lube oil by silicon (dust) is a major cause of accelerated wear

fter oxygen, silicon is the most abundant element in the earth's crust. Silicon does not occur naturally in elemental form but rather combined with oxygen in a compound called silica (silicon dioxide). Silica occurs in a free form (quartz, sand, etc.) or combined with a variety of metallic oxides, in which case it is called a silicate (eg. Felspar). Another class of silicon compounds that should not be confused with silica and silicates is silicones. Silicones are man-made



organic compounds that find extensive application in the polish, paint and lubrication industries.

Silica and silicates make up a large proportion of the earth's crust and as such are present at high concentrations in natural soils and dusts. It is for this reason that silicon is used as the main indicator of dust entry into a component. There have been several studies done on the causes of premature wear in components. The figures vary from study to study but one thing is clear: external contamination of lube oil by silicon (dust) is a major cause of accelerated wear.

The South African climate generally is one of low rainfall with resultant high dust levels. Particles of airborne sand and dust vary in size, shape and abrasive properties. In an engine the ingress of atmospheric dust takes place primarily through the air intake. Efficient air filters remove 99 % of the dust that an engine ingests. The

Smallest dimension

Largest dimension

Dust particles

Dust particle

remaining 1 % consists of very small dust particles that pass through the air filter. These vary between submicron size particles to particles up to 10 microns in size. This dust will pass between piston, rings and cylinder and eventually become suspended in the lubricating oil.

It is the particle that has its smallest dimension of a similar size to the clearance involved that does the maximum damage. A particle smaller than the clearance will pass straight through doing little harm; a particle larger than the clearance will be unable to enter and do any damage. (See diagram on Page 1).

In an engine the clearance between the piston ring and liner bore is extremely small, therefore it is the small light airborne dust particles which are the biggest threat when a leak occurs in an induction system.

Under ideal conditions the working surfaces of a component are kept apart by a thin film of oil. This oil film prevents direct contact between the surfaces, reducing the amount of friction and the rate of wear. The oil film will also absorb shock loads and help distribute the load over the whole surface. The introduction of even a small amount of dust into this environment will seriously disrupt this. Once the dust particle has entered the oil film it forms a direct link between the two surfaces, nullifying the effect of the oil film.

The first and immediate effect is a "scratching" of the surface as the particle is dragged and rolled across the surfaces. The second and potentially more serious problem is that once the dust particle is introduced in between the two surfaces, it changes the loading of the surface from an even distribution to a point load concentrated on the particle with a tremendous increase in pressure at this point. The increase in pressure causes a deflection of the surface, which will eventually result in metal fatigue and the surface breaking up.

The solution is to keep the dust out. To do this, design engineers use air cleaners, breathers and seals at any point that dust may enter.

Air cleaners filter air as it is drawn through a system, eg. in engines, compressors, etc. They have to deal with large volumes of air, as an engine needs up to 2000 litres of air to burn 1 litre of fuel efficiently. The most common type of air cleaners have three main components: a centrifugal precleaner, a large pleated paper element and a smaller paper or cloth "safety element".

The precleaner consists of radial fins and a collection bowl. The fins cause incoming air to swirl rapidly around the inside of the housing. The heavier dust particles are thrown outward by centrifugal force and are channelled into the dust collection bowl. Some bowls have an automatic discharge valve, other bowls have to be removed from time to time to clean out the accumulated debris before it overflows into the filter housing.

The main filter element traps the remaining dust particles as the air is drawn through the paper pleats.

The smaller safety element is fitted after the main element in case the main element is damaged in any way. Its purpose is to trap any dust introduced when the main filter is changed. It does not filter as effectively, however, nor can it hold the same volume of dust.

Breathers are used to allow air to flow in and out of a component. As a component's temperature increases in operation, the internal air expands with the increase in temperature with a resultant increase in pressure. If this

An engine needs up to 2000 litres of air to burn 1 litre of fuel efficiently.



Air cleaner

air was not allowed to vent to the atmosphere, the build-up in pressure would force the air out at the weakest point, normally the seals. As the component cools down after operation, air is once again drawn in through the breather. If it is unable to draw in air, for example if the breather is blocked, then air will be pulled in past the seals with the



Front crankshaft oil seal

danger that it may draw dust into the seal at the same time.

Seals prevent oil from entering or leaking out of a component wherever there is a danger of this happening. There are many different types of seals in use today, but as a rule of thumb "if oil can get out, dust can get in". A leaking seal should always be replaced.



Engine breather of turbocharged engine

Using oil analysis to detect dust early

Before the use of oil analysis, a dust entry problem would go undetected until a routine stripdown or a failure occurred. Even then, often the wear would be attributed to lubricant breakdown or normal wear and tear. With the use of oil analysis the picture changes. As soon as a dust entry problem occurs there is an increase in the silicon level of the oil

and an acceleration of the wear pattern. As long as the oil samples are being taken at regular intervals in the correct manner, the dust entry will be detected at a very early stage. If effective corrective action is taken, the life of the component will be significantly increased, reducing maintenance costs.

Engines are at high risk to dust entry as they take in large volumes of air. It is beyond the scope of this article to discuss every possibility in all components, so engines will be used as an example. Engines are at high risk to dust entry as large volumes of air are taken into the system and the close tolerances make it susceptible to even the smallest dust particle.

When an engine has a dust entry problem the type of wear that takes place is related to the manner in which the dust enters. Therefore by examining the type of wear taking place it is possible to discover how the dust is entering the system. When studying an oil analysis report there are four possible wear patterns: 1 Normal wear



Engine air cleaner system

3 Increased bottom-end wear

4 All wear rates increased.

Normal wear

2 Increased top-end wear

It is unlikely that there will be a dust entry problem without an increase in wear rates. If normal wear patterns combine with high silicon readings, there are two main possibilities:



If there is still doubt as to what caused the high silicon reading, a check sample should be taken.

Was the oil changed when the first sample was taken?



Send a check sample and, as a precaution, change the oil.

Send a check sample only after the engine has run for 50 hours or 1000 km.

YES

The close tolerances in an engine make it susceptible to even the smallest dust particle.

2 Increased top-end wear

Increased top-end wear is caused by airborne dust that has been drawn into the combustion chamber being forced down between the ring, piston and cylinder. This is caused by a defective air cleaner or a damaged induction system.

Action to be taken

Inspect the air filter element thoroughly, and check its seals and support frame for damage and distortion. Check the pleats for damage. If there is any doubt about a filter element, it should always be changed.

Next, check the induction hosing for damage, cracks, etc, and make certain that all hose clamps are secure. The breather and compressor are often connected to the induction system but are frequently overlooked. Check that both are functioning normally and their hoses are sound and secure.

Next, check the inlet manifold for cracks, and check that the gaskets are sound and secure.

Was a leak found?

A defective air filter can cause increased top-end wear.

1000 km.

NO Run the engine at idle and block off Determine the condition of the the air intake. The engine should stall engine. Check compression and within three seconds. If the engine blowby. Repair the leak. does not stall, listen carefully at the joints for air being sucked in. Take a check sample after 50 hours or

Abnormal

YES

Monitor the oil consumption as a safeguard.

Normal

Schedule to have the piston rings replaced and the piston and liners examined.

Increased bottom-end wear 3

This indicates that dirt is getting into the lube oil directly and not past the pistons and rings. The likely sources are:





This is the worst case. Carry out all checks for top and bottom wear. Several other checks must also be done:



Was any repair work done to the engine?

It is possible that the increased wear rates are due to a "rebedding in" process and silicon comes from contamination while the engine was open for repairs.



Piston torching

This is a rare occurrence but if a piston is torched by a misdirected or badly timed spray from an injector nozzle, silicon is released from the piston itself and all the wear rates will be increased. (Silicon is alloyed to aluminium to reduce its rate of expansion.)

Examine the oil filter for excessive dirt.

Produced by Wearcheck Africa.

NATAL 9 Le Mans Place, Westmead. P.O. Box 15108, Westmead, 3608. Tel: (031) 700-5460 Fax: (031) 700-5471

TRANSVAAL 3 Bedford Plaza, Skeen Boulevard, Bedfordview, 2008. P.O. Box 75416, Garden View, 2047. Tel: (011) 455-3342 Fax: (011) 455-4909